

#### Galltec Mess- und Regeltechnik GmbH

D-71145 Bondorf · Germany
Tel. +49 (0)7457-9453-0 · Fax +49 (0)7457-3758
E-Mail: sensoren@galltec.de · Internet:www.galltec-mela.de

#### **MELA Sensortechnik GmbH**

D-07987 Mohlsdorf-Teichwolframsdorf · Germany Tel. +49(0)3661-62704-0 · Fax +49(0)3661-62704-20 E-mail:mela@melasensor.de · Internet: www.galltec-mela.de





D Series
Sensors for
Humidity and Temperature Measurement
With calibrated dModul

# Type DK Industrial version, duct version Optional display

- dynamic MELA<sup>®</sup> humidity sensing element
- · output of all hx values
- calibrated dModul for humidity and temperature measurement
- · in situ alignment
- · easy to install
- operating temperatures up to 80°C

The core part of the D Series is the digital calibrated dModul, which processes the measurement values of relative humidity and temperature individually. The values are compared to the calibration values stored in the dModul and communicated digitally to the transmitter electronics, where they are processed to standardised current and voltage signals.

The housings of the industrial versions provide protection in accordance with IP 65. Only a single screw is required to close it securely.



#### **Technical data**

# **Humidity**

measuring element	capacitive MELA FE09
output range	0100 %RH
measuring uncertainty 1090 %RH at 104 < 10 %RH or > 90 %RH at 104	
influence of temperature <10°C	or >40°C ±0.05 %RH/K

### **Temperature**

measuring element	Pt1000 1/3 DIN
output ranges	0+50°C -30+70°C 0+100°C further ranges on request
measuring uncertainty sensors with active temperature sign with voltage output at 1040°C with current output at 1040°C	±0.2 K ±0.3 K
influence of temperature <10°C or >	>40°C ±0.01 K/K

#### **Electrical data**

outputs	01 V 010 V 420 mA
	passive temperature outputs on request
voltage supply	see type survey
consumption of election (voltage output)	etronics typ. 7 mA
load resistance (voltage output)	≥10 kΩ
load R <sub>L</sub> (current output)	$R_{L}(\Omega) = \frac{\text{voltage supply - 10 V}}{0.02 \text{ A}} \pm 50 \Omega$
electromagnetic	ref. EN 61326-1

electromagnetic ref. EN 61326-1 compatibility and EN 61326-2-3

#### **General data**

General data		
measuring medium	air, pressurele	ess, non-aggressive
max. air speed protective cage w. mo (basic equipment)	embrane	10 m/s
min. air speed		≥ 0.5 m/s
operating temperatures transformer part/housin (v at the sensor head	g (with display) vithout display)	-30+80°C -40+80°C -40+80°C
storage temperatures		-40+85°C
connection wire diameter per contotal diameter cable		connecting terminals max. 1.5 mm <sup>2</sup> 4-8 mm
degree of protection / mea protective cage w. me (basic equipment) PTFE sinterd filter (o	embrane	IP 30
degree of protection / hou	sing	IP 65
material of housing		PC


#### **Options**

display	2 lines
	3 digits + 1 decimal place
	display approx. 21 x 40 mm <sup>2</sup>
	digit height approx. 8 mm

#### hx Values, selectable for two outputs

relative humidity	0100 %RH
temperature	-30+70°C 0100°C 050°C further ranges on request
dew point temperature	-2070°C
enthalpy	080 kJ/kg
mixing ratio	0100 g vapour/kg dry air
absolute humidity	020 g/m³ or 0100 g/m³
wet-bulb temperature	-1050°C

## Load at current output



# Type survey DKF Humidity sensor

Standard length of sensor tube

Special lengths

Туре	Housing duct version
DKF	optional display

Physical value	Output signal corresponds to
relative humidity	0100 %RH

220 mm

48 mm or 140 mm

Electrical	Voltage
outputs	supply <b>U</b> B
01 V	630 V DC 626 V AC
010 V	1530 V DC 1326 V AC
420 mA	1030 V DC

Type survey DKK Humidity and temperature sensor

Туре	Housing duct version
DKK	optional display

Physical value	Output signal
selectable for 2 outputs	corresponds to
relative humidity	0100 %RH
temperature	-30+70°C 0+100°C 0+50°C
dew point temperature	-2070°C
enthalpy	080 kJ/kg
mixing ratio	0100 g vapour /kg dry air
absolute humidity	020 g/m³ 0100 g/m³
wet-bulb temperature	-10+50°C

Electrical	Voltage
outputs	supply U <sub>B</sub>
01 V	630 V DC 626 V AC
010 V	1530 V DC 1326 V AC
420 mA	1030 V DC


Passive temperature output available on request.

# Product key D Series

Thanks to the hx-converter the D Series offer a wide range of types.

The product no. of each type consists of a 16-digit alpha numeric code that descibes the sensor

The product key enables you to order the exact type of sensor for your application.




#### Order codes for the D Series product key

Digit	Technical Data	Options	Order code
1	Series	D Series	D
2	Design	Duct version	K
		Wall mounting version	W
		Room version	I
3	Physical outputs	Humidity sensor	F
		Sensor with 2 active output signals	K
		Sensor with 1 active and 1 passive ouput signal	С
		Temperature sensor	Т
4	Ouput signals	2x 01 V or 1 x 01 V and 1 x passive	1
		2x 010 V or 1 x 010 V and 1 x passive	2
		2x 420 mA or 1 x 420 mA and 1 x passive	3
5 6	Working conditions / special version	Standard	00
7 8	Measured variable and ouput range 1	Relative humidity 0100 % RH	F1
	and	Temperature -3070°C	37
9 10	Measured variable and ouput range 2	Temperature 0100°C	01
		Temperature 050°C	05
	A survey of passive output signals for temperature is available at the manufacturer. Complete order number on demand.	No signal	00

Digit	Technical Data	Options		Order code
7 8	Measured value and output range 1		D2	
9 10	Measured value and ouput range 2	Enthalpy 080 kJ/kg		H1
3 10	ivicasureu value ariu ouput rarige z	Mixing ratio 0100 g/ kg dry air		Х3
	hx-values (as shown on the right)	Absolute humidity 0100 g/m³		A3
	only available for industrial versions DKK and DWK	Absolute humidity 020 g/m³		A1
		Wet bulb temperature -1050°C		W1
		No signal		00
11	Operating voltage	630 V DC or 626 V AC / Sensors w. 01 V output signal		6
		1530 V DC or 1326 V AC / Sensors w.	010 V output signal	F
		1030 V DC for DK and DW w. 420 1025 V DC for DI w. 420	mA output signal mA output signal	А
12 13	Measuring head / Filter / Diameter ZE08: protective cage, plastic, w. membrane, Ø 12 mm		08	
		ZE05: sintered PTFE filter, IP54, Ø 12 mm		05
14 15	Design description / options	Duct version without display	220 mm sensor tube	00 G
	and	Duct version with display	220 mm sensor tube	0D G
16	Sensor tube	Version for wall mounting without display 50 mm sensor tube		00 1
		Version for wall mounting with display	50 mm sensor tube	0D 1
		Room version without display	-	00 0
		Room version with display	-	0D 0


#### Order example




#### **Accessories**

Product n°	Description
ZE05	sintered filter made of fine-pored PTFE, IP 65
20.045	fixing flange, synthetic material, with fixing mechanism for easy sensor mounting and removal for sensors Ø 12 mm, with rubber sealing (enclosed in delivery)
ZE 31/1-12 ZE 31/1-75	humidity standard to check the accuracy of the sensor at 12 %RH humidity standard to check the accuracy of the sensor at 75 %RH
ZE 31/1-33 ZE 31/1-84	humidity standard to check the accuracy of the sensor at 33 %RH humidity standard to check the accuracy of the sensor at 84 %RH
ZE36	testing adapter for humidity standards for sensor tubes Ø 12 mm


#### **Dimensions**



# **Drilling pattern**




# Fixing flange




#### **Connection diagrams**


#### **DKF 4...20 mA**




#### DKK 2 x 4...20 mA




#### **DKF 0...1 V DC**




#### DKK 2 x 0...1 V DC



#### **DKF 0...10 V DC**



#### DKK 2 x 0...10 V DC



#### **ESD** protection advice

The sensors of the D Series contain components, which can be damaged by the effects of electrical fields or by charge equalisation when touched.

The following protective measures must be taken when the housing of the sensor is to be opened for connection or in situ alignment:

- Before opening the housing of the sensor, ensure electrical potential equalisation between you and your environment.
- Pay particular attention to ensure that this potential equalisation is maintained while you are working with the opened housing.

#### In situ alignment

During the in situ alignment the sensor does not necessarily have to be taken out of the control circuit.

We offer humidity standards for alignment of the sensors (page 3: accessories).

Before calibrating the sensor, standards should remain at least 2 hours on the sensors.

The temperature must remain constant during this time. For the correct temperature according to the humidity standard used, please refer to data sheet F5.2 Humidity Standards.

During calibration temperature and humidity must remain constant.

During calibration, especially during storage of data, uninterrupted power supply of the sensor must be provided.

During calibration the following measurement ranges are shown on the display/ are used for calibration:

CH 1: all sensors always: relative humidity, measuring range 0...100 % RH.

CH 2: sensors the programmed temperature range, unaltered

with relative humidity RH output (CH1) and temperature °C output (CH2)

sensors the standard temperature measuring range of -40...85°C

with other hx-values outputs

The accuracies shown in the technical data of this data sheet refer exclusively to works calibration.

Command		Operation	Transmitter / LED
default attention: all user adjustments will be reset.	possible only when adjustment mode is off. (LED must not be lit.)	press buttons UP and DOWN simultaneously for at least 8 sec.	until LED lights up for 1 sec.
calibration mode	selection of adjustment mode	press button DOWN for at least 3 sec.	until LED blinks 1 time per second
	T	T.	1
selection of type of calibration	humidity 1-point-adjustment (offset)	no further command necessary	LED blinks 1 time per second.
	humidity 2-point-adjustment lower point at 12 %RH and 2030°C humdity standard ZE31/1-12	press button DOWN 1 time shortly	LED blinks twice per second.
	humidity 2-point-adjustment upper point at 75 %RH and 2030°C humdity standard ZE31/1-75	press button DOWN twice shortly	LED blinks 3 times per second.
	temperature 1-point-adjustment	press button DOWN 3 times shortly	LED blinks 4 times per second.
confirmation of selection		press button DOWN for at least 3 sec.	until LED lights up permanently
adjustment		buttons UP / DOWN: (press shortly) +/- 0.1 %RH respectively +/- 0.1°C per keystroke	
saving		press button DOWN for at least 3 sec.	until LED is off
program termination (at any time)		press button UP for at least 3 sec.	until LED blinks 6 times and then switches off.

#### **Mounting instructions**

Position	Install the sensor at a place where characteristic levels of humidity occur. The measuring chamber should be located in streaming air. Avoid installation next to heaters, doors or on outer walls. Avoid places exposed to the sun.
	Do not position the sensor where ingress of water could occur.
	To close the housing securely turn screw until dead stop.
	We recommend that you lay the connection lines in a loop so that any water that may be present can run off.
	Not reaching the given minimum air speed can lead to measurement errors.
Fixing flange	The hole pattern of the fixing flange (included in the delivery) is located on the packaging of the sensor. In order to fix the sensor in the flange simply press the clip open (by hand or using tongs). The sensor can be fixed in the flange at any position.
Connection	The electrical connection must be carried out by qualified personnel only.
	The sensor contains sensitive electrical components. When opening the housing, make sure you comply with the electrostatic discharge precautions (ESD).
	Please pay attention to the ohmic resistance according to the operating voltage (see diagram on page 2) when using sensors with a current output. Else measurement errors may occur.
	Lines to and from the sensor must not be installed parallel to strong electromagnetical fields.
	If there is any chance of an electrical surge, please install surge protection devices.
User instructions	
Dew formation  Dew formation and splashes do not damage the sensor, although meas readings are corrupted until all moisture on and around the sensing elem dried up completely.	
If necessary, soiled filters can be screwed off and rinsed carefully. Bear in n sensors wil not measure accurately until filters are completely dry. Please rotective baskets touch the highly sensitive humidity sensing element. Please ensure that the rature sensing element does not touch the sensitive surface of the humidity element.	
Cleaning of the capacitive humidity sensing element	Loose dust can be carefully cleaned off the humidity sensing element using distilled water or by blowing the dust carefully off. Please do not touch the highly sensitive humidity sensing element. Please ensure that the temperature sensing element does not touch the sensitive surface of the humidity sensing element.
Damaging influences	Depending on type and concentration, agents that are corrosive and contain solvents, can result in faulty measurements and can cause the sensor to break down. Substances deposited on the sensor (e. g. resin aerosols, lacuer aerosols, smoke deposits etc.) are damaging as they eventually form a water-repellent film.

This information is based on current knowledge and is intended to provide details of our products and their possible applications. It does not, therefore, act as a guarantee of specific properties of the products described or of their suitability for a particular application. It is our experience that the equipment may be used across a broad spectrum of applications under the most varied conditions and loads. We cannot appraise every individual case. Purchasers and/or users are responsible for checking the equipment for suitability for any particular application. Any existing industrial rights of protection must be observed. The quality of our products is guaranteed under our General Conditions of Sale. Data sheet DK\_EN. Issue: June 2015. Subject to modifications.